

SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SF340/83.

SAAB SF340 Series Aeroplanes

AD/SF340/83

Replacement of Hydraulic Hoses

1/2010

Requirement: CANCELLED.

This AD is cancelled on 28 January 2010.

Background: This directive required the replacement of hydraulic hoses in accordance with SAAB SB 340-29-022 and Swedish AD 1-170. Following replacement of hoses a life limit was introduced that is now included in the mandatory requirements of Section F - Systems Life Limited Parts of the SAAB 340 Maintenance Review Board (MRB) report. This AD is therefore cancelled.



Mike Higgins
Delegate of the Civil Aviation Safety Authority

5 January 2010