

Bell Helicopter Textron 212 Series Helicopters

---

**AD/BELL 212/9**

**Stabilizer Bar Outer Tube - Inspection**

**1/82**

CANCELLED.

Background: The applicable service bulletin 212-76-4 is inactive; there have been no reported defects; and daily visual inspection of the stabilizer bar tubes is called up in the Bell 212 Maintenance Manual.