

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 212/44.

---

### Bell Helicopter Textron 212 Series Helicopters

**AD/BELL 212/44**

**Swashplate Outer Ring**

**4/2009**

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD, issued in 1990, required inspection of the swashplate outer ring in accordance with Bell Alert S.B. No. 212-90-61 to identify parts that have a casting defect created during manufacture. The AD compliance was prior to 25 May 1990. As all aircraft would have been inspected by now, the AD is no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

16 February 2009