

Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters

AD/DAUPHIN/38 Front Passenger Door Jettison Mechanism 5/94

Applicability: Model SA 365 N helicopters, versions N, N1, and N2 which have not been modified per modification AMS 365A07-56B15, with serial numbers 6008, 6033, 6083, 6084, 6085, 6093, and helicopters with serial numbers higher than 6120; except 6282 through 6299 and those delivered after 25 October 1993.

Requirement: Action in accordance with Eurocopter Mandatory SA 365 SB No.01.38.

Note: DGAC AD 94-052-035(B) refers.

Compliance: As specified in the Requirement Document.

Background: A door jettison mechanism anomaly was found during production.