

---

**AIRWORTHINESS DIRECTIVE**

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 269/14.

---

**Schweizer (Hughes) 269 Series Helicopters**

**AD/HU 269/14**

**Battery Support Bracket - Inspection**

**11/2009**

Requirement: CANCELLED.

This AD is cancelled on 22 October 2009.

Background: This AD raised, in 1967, required an inspection of battery support bracket P/No. 4805-3 for cracking in the forward attachment bolt area. Compliance was required at intervals not exceeding 25 hours TIS.

As there are no records related to this AD contained in the mandatory defect reporting system this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

4 September 2009