

Schweizer (Hughes) 269 Series Helicopters

---

**AD/HU 269/23                      Main Rotor Gear Drive Assembly - Inspection                      11/81**  
**Amdt 8    and Replacement**

Applicability:    All models fitted with P/N 269A5175, 269A5175-3 or 269A5175-5 main rotor gear drive, incorporating P/N 269A5179 or 269A5179-3 drive shaft.

Document:        Hughes SIN N-179.

*Note: FAA AD 81-17-04 refers.*

Compliance:    In accordance with the requirement document.

Background:     The Directive is raised in issue to reflect current manufacturers data and FAA requirements. Hughes SIN N-179 supersedes N-114-3 N-143, and additionally reduces the life of P/N 269A5179 or 269A5179-3 shaft and coupling assemblies. Installation of P/N 269A5194 carrier assembly(N-142-1) is now mandatory.