

Schweizer (Hughes) 269 Series Helicopters

---

**AD/HU 269/29                      Tail Rotor Blade Assembly - Inspection                      12/68**

Applicability:    All models with tail rotor blade assemblies S/Nos up to and including 126-3312.

Document:        Hughes SIN N-58.

Compliance:     Within 25 hours time in service after 9 December 1968 and thereafter at intervals not exceeding 25 hours time in service.