## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

## **AIRWORTHINESS DIRECTIVE**

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 269/72.

## Schweizer (Hughes) 269 Series Helicopters

## AD/HU 269/72 Idler Pulley Support Bracket - Inspection 6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, raised in 1988 against McDonnell Douglas Helicopter Company Service Information Notice (SIN) No. EN-40 and FN-29, required a modification to prevent cracking at the outboard ends of the horizontal stabiliser tabs as a result of vibration. Compliance was required by 1 March 1988.

As all affected aircraft would have been modified long ago, this AD is no longer required.

David Villiers Delegate of the Civil Aviation Safety Authority

17 April 2009