

---

**AIRWORTHINESS DIRECTIVE**

---

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 269/75 Amdt 2.

---

**Schweizer (Hughes) 269 Series Helicopters**

**AD/HU 269/75                      Tail Rotor Blade Root Bushing Holes and                      2/2004**  
**Amdt 2                                              Retention Bolts**

Requirement:    CANCELLED.

Background:      The manufacturer has incorporated the requirements of this AD into the current revision of the IPC, HMI and Flight Manual for the affected rotorcraft.



David Villiers  
Delegate of the Civil Aviation Safety Authority

7 January 2004