
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 369/44 Amdt 1.

McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

**AD/HU 369/44
Amdt 1**

**Collective Torque Tube and Bungee
Support Brackets - Inspection**

6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, raised in 1980 against Hughes Service Information Notice (SIN) No. HN-54.1, required an inspection for cracks of the bungee and collective torque tube support brackets. Compliance was required within 100 hours TIS after 30 June 1980.

As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

17 April 2009