COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Sikorsky S-76 Series Helicopters

AD/S-76/16 Amdt 2	Main Rotor Blade Root End - Inspection 4/85 for Fatigue Cracking
Applicability:	All models fitted with main rotor blades P/N 76150-09000 or 76150-09100.
Requirement:	Sikorsky S76 Alert Customer Service Bulletin no. 76-65-18C.
Compliance:	As detailed in requirement document. Inspections carried out in accordance with the previous issue of this directive, meet the requirements of this issue.
Background:	The directive has been amended to nominate ACSB 76-65-18C as a more appropriate requirement document than the Composite Materials Manual. FAA AD 84-10-02 also refers to this subject.