

Sikorsky S-76 Series Helicopters

AD/S-76/23

**Main Rotor Servo Actuators
Internal Leakage Checks**

8/83

CANCELLED.

Background: Internal leakage check requirements called out by this Directive are now adequately covered in the Sikorsky (a) Flight Check Procedures Manual, (b) Airworthiness Limitations and Inspection Requirements Manual.