

Sikorsky S-76 Series Helicopters

---

**AD/S-76/44**

**Tail Rotor Blade Disbonding**

**8/92**

CANCELLED.

Background: The Manufacturer has incorporated the AD requirement Document inspection requirements and information into the Airworthiness Limitations and Inspection Requirements, Chapter 5, and the Composite Materials Manual. Sikorsky ASB 76-65-39A refers.