

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/S-76/48.

---

### Sikorsky S-76 Series Helicopters

#### **AD/S-76/48            Main Gearbox Lower Housing Jet Port Liners    7/2009**

Requirement:    CANCELLED.

This AD is cancelled on 2 July 2009.

Background:    This unique Australian AD raised in 1987 against Sikorsky Alert Service Bulletin (ASB) 76-66-11 required an inspection to ensure that all magnesium liners of the main gearbox lower housing oil pressure jet ports were correctly pinned.

Compliance was: Within 50 hours TIS after 15 October 1987, inspect in accordance with Section 2 of the requirement document.

This AD has been sufficiently promulgated for the affected Helicopters to have been inspected by now; therefore this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

18 May 2009