

Eurocopter AS 332 (Super Puma) Series Helicopters

---

**AD/S-PUMA/13**

**Tail Rotor Drive Shaft**

**10/99**

CANCELLED.

Background: The requirements of this Directive have now been incorporated into the Eurocopter AS332 Master Servicing Recommendations (PRE) and are therefore deemed to be mandatory for all Australian operators. This Directive is therefore cancelled with effect from 7 October 1999.