## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Allison Turbine Engines - 250 Series

## AD/AL 250/53 Amdt 1

## **Compressor Mount Assembly**

2/86

Applicability:

Model 250-C28 and -C30 series engines which incorporate compressor mount assemblies P/N 6896021, 6898966 or 6898611 with serial numbers as listed in the Requirement Document.

Requirement:

- 1. Inspect compressor mount assemblies P/N 6896021, 6898966 and 6898611 in accordance with Allison CEB-A-72-2080/3081 dated 15 September 1982.
- 2. Replace compressor mount assemblies P/N 6896021, 6898966 and 6898611 with mount P/N 23007217 in accordance with Allison CEB-72-2085/3085 Rev. 1 dated 30 April 1985.

Note: FAA AD 85-25-08 Amendment 39-5189 refers.

Compliance:

Part 1. In accordance with the Requirement Document.

Part 2. At the next compressor assembly overhaul or repair after 28 February 1986 but not later than 30 November 1986.

Background:

This Directive is amended to include the FAA AD 85-25-08 mandatory introduction of the improved compressor mount assy.