
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/ALF/15.

AlliedSignal (Lycoming) Turbine Engines - ALF502 and LF507 Series

AD/ALF/15

Fuel Manifold Inspections

2/2010

Requirement: CANCELLED.

This AD is cancelled on 11 February 2010

Background: A State of Design airworthiness directive issued on or after 1 October 2009 is defined as an airworthiness directive per CASR Part 39.001A. The requirements of this airworthiness directive which referred to FAA AD 97-11-05 have been superseded by FAA AD 2009-26-06 issued on 7 January 2010.



Mike Higgins
Delegate of the Civil Aviation Safety Authority

20 January 2010