

General Electric Turbine Engines - CF6 Series

AD/CF6/31

**Fan Stator Case Stiffening Ring
and Stage 1 Fan Shroud**

9/94

Applicability: General Electric CF6-45/-50 series engines.

Requirement: Action in accordance with the technical requirements of FAA AD 94-08-05.

Note: General Electric CF6-50 Service Bulletin 72-573 refers.

Compliance: As specified in the FAA AD with an effective date of 18 August 1994.

Background: The FAA AD was raised as a result of an uncontained stage one fan blade failure which resulted in an inflight engine shutdown and damage to the aircraft.