

AlliedSignal (Lycoming) Turbine Engines - LTS 101 Series

---

**AD/LTS/7  
Amdt 2**

**Power Turbine Rotor**

**3/91**

- Applicability: All LTS 101 series engines fitted with Power Turbine Rotors part number 4-141-070-XX.
- Requirement: Action in accordance with Textron Lycoming SB No LT 101-72-00-0093 Rev. 5  
*Note: FAA AD 87-11-09 refers.*
- Compliance: Unless previously accomplished; within 50 hours time in service from 21 March 1991, and thereafter at intervals not to exceed 50 hours or 300 cycles, whichever occurs first.
- Background: This Directive has been amended to reflect the manufacturers latest revision to the Requirement Document detailed in FAA AD 87-11-09. This amendment also reflects the release of an individually bladed power turbine rotor. LTS101 series engines fitted with individually bladed power turbine rotors are not affected by this Directive.