

AlliedSignal (Lycoming) Turbine Engines - LTS 101 Series

AD/LTS/8

Number 4 Bearing Distress

3/88

CANCELLED.

Background: This Directive is cancelled because the Requirement document has been superseded by and incorporated into FAA AD 84-26-10 which is the Requirement document of new AD/LTS/9 which is issued concurrent with this cancellation notice.