

Pratt and Whitney Canada Turbine Engines - PT6A Series

AD/PT6A/25

Sundstrand Fuel Pump Drive Wear

11/91

CANCELLED.

Background: The requirement for periodic inspection of the fuel pump drive for evidence of wear is now reflected in the appropriate Pratt and Whitney Canada PT6A Maintenance Manual.