

Pratt and Whitney Canada Turbine Engines - PT6A Series

AD/PT6A/29

Compressor Bleed Valve

1/2000

CANCELLED.

Background: This directive was issued to require a once only inspection of PT6A-114A compressor bleed valves. The inspection requirement was also the subject of a warranty program issued by the engine manufacturer. That program included providing replacement valves free of charge. Advice received indicates all applicable engines have been inspected.