

AlliedSignal (Lycoming) Turbine Engines - T53 Series

AD/T53/11	Replacement Of Compressor Rotor Discs and Impeller Assembly	1/86
------------------	--	-------------

Applicability: All models T5309C, T5311A, T5311B engines.

Document:

1. Lycoming SB No. 0033; or
2. FAA AD 74-09-03; or
3. AD/LYC-T/12.

Compliance: Before 28 June 1974