
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/TPE 331/21.

AlliedSignal (Garrett/AiResearch) Turbine Engines - TPE 331 Series

AD/TPE 331/21

**Fuel Pump Spline Wear
Inspection and/or Replacement**

10/2009

Requirement: CANCELLED.

This AD is cancelled on 24 September 2009.

Background: This unique Australian AD specified inspections in accordance with Airesearch SB No. 73-0033 Rev 5 at intervals between 3000 and 3200 hours. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

14 August 2009