

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/DHC-6/25 Amdt 1.

---

### DHC-6 (Twin Otter) Series Aeroplanes

**AD/DHC-6/25  
Amdt 1**

**Main Undercarriage Platen Attach  
Link Fittings - Inspection**

**12/2008**

Requirement: CANCELLED.

This AD is cancelled on 20 November 2008.

Background: This AD was raised in 1971 against De Havilland Canada Service Bulletin No. 6/226 Rev.A, requiring an inspection and modification of the main undercarriage platen attachment link fittings following two reports of cracks during routine inspections.

As all affected aircraft would have been inspected and modified by now, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

8 October 2008