

Dornier DO-27 Series Aeroplanes

AD/DO27/12

Horizontal Tail Bearing Fitting Rivets

13/96 DM

Applicability: All Series all Serial Numbers.

Requirement: Action in accordance with Daimler Benz Aerospace/Dornier SB1140-0000 dated 29 September 1995.

Note: LBA AD 96-271 refers.

Compliance: Within 30 days after 09 October 1996.

Background: Loosening of rivets is possible at the bearing flange, and “L” profile and profile of the frame.