

Fuji FA-200 Series Aeroplanes

AD/FA-200/19
Amdt 2

Rudder Pedal System

11/89

Applicability: All models FA-200 with S/Nos. 12 to 297.

Requirement: Action in accordance with FHI SB No. 200-002 Rev C.

Note: JCAB AD TCD-1455A-1-89 refers.

Compliance: Within 50 hours time in service after 3 December 1984 or prior to the first flight during which aerobatics are to be performed, whichever is earlier. Thereafter at:

- a. each inspection for Maintenance Release issue, or
- b. periods not to exceed 1000 hours time in service if Technical Bulletin 200-22 is embodied.

Background: Overtravel of the rudder pedals and incorrect rudder control system operation has been experienced. Amendment 2 introduces a relieving modification to extend the inspection periodicity to 1000 hours.