

Airparts (NZ) Ltd. FU 24 Series Aeroplanes

AD/FU24/46

**Brake Torque Plates - Inspection
and Modification**

5/73

Applicability: All model FU24-950.

Document: Air Parts SB No. AP.101.

Compliance: Inspect at intervals not exceeding 100 hours time in service until modified. Modify within 300 hours time in service after 31 May 1973.