

GAF N22 and N24 Series Aeroplanes

AD/GAF-N22/41

**Emergency Exit Door Lock
Mechanism - Inspection**

5/81

Applicability: All models N22 and N24.

Document: GAF Telex Nomad Alert SB ANMD 52-2.

Compliance: Unless already accomplished, within 10 hours time in service after 16 April 1981.

Background: Instances have occurred in which the lock mechanism spindle on the emergency exit door has been incorrectly positioned before fitting the handle.