

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/L.40/6 Amdt 1.

---

### Meta Sokol L.40 Series Aeroplanes

**AD/L.40/6**                      **Elevator Control System - Modification**                      **9/2009**  
**Amdt 1**

Requirement:      CANCELLED.

This AD is cancelled on 27 August 2009.

Background:      This unique Australian AD specified installation of the lower elevator cable assembly with the turnbuckle at the forward end. Compliance was required before September 1971. The AD was not based on a manufacturer's service document. The AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

30 June 2009