

Mooney M20 Series Aeroplanes

AD/M20/9

Rudder Drain Hole - Modification

9/67

Applicability: All model M20F with S/Nos. 660003, 660004 and 670001 to 670030.

Document: Mooney SB No. M20-149.

Compliance: Within 100 hours time in service after 7 September 1967.