

Mooney M20 Series Aeroplanes

AD/M20/38 **Fuselage Tubular Structure - Modification** **2/80**

Applicability: All model M20K with S/Nos. 25-0001 to 25-0247.

Document: Mooney SB No. M20-220.

Compliance: Before 1 July 1980.

Background: The manufacturer advises of the possibility of the lower fuselage longeron buckling under severe positive gust conditions.