

Mooney M20 Series Aeroplanes

AD/M20/44

Baggage Door Inside Latch

2/89 DM

Applicability: M20J S/No 24-0084, 24-0378 to 24-1645 and 24-3000 to 24-3056 M20K S/No 25-0001 to 25-1160.

Requirement: Action in accordance with Mooney Aircraft Corporation SBM20-239.

Note: FAA AD 88-25-11 refers.

Compliance: Within 25 hours time in service after 11 January 1989.

Background: There have been reports overseas of in-flight opening of the baggage door, one of which involved fatalities.