

Maule M-4 Series Aeroplanes

AD/ML-M4/13

**Horizontal Tail to Fuselage Front Attach
Tubes - Inspection and Modification**

3/80

- Applicability: All M-4 series with S/Nos. as referenced in Maule Aircraft Corporation SB No. 1.
- Document: Maule Aircraft Corporation SB No. 1.
- Compliance: Unless already accomplished, within 100 hours time in service after 31 October 1979.
- Background: There is a possibility that the fuselage tube attaching the front attach point of the horizontal tail may be cracked.