

Aerospatiale Rallye Series Aeroplanes

---

**AD/MSR/16**

**Firewall Engine Mount Attachment  
Fittings - Inspection**

**8/71**

Applicability: All models.

Document: Rallye SB No. 86.

Compliance: Within 100 hours time in service after 30 September 1971 and there after at intervals not exceeding 100 hours time in service.