

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/1 Lagging of Engine Air Bleed Pipes - Modification 7/69

Applicability: All models.

Document: Mitsubishi SB No. 070.

Compliance: Before 7 September 1967.