

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/17**  
**Amdt 4**

**Elevator Trim Tab Bracket - Inspection  
and Replacement**

**1/85**

- Applicability: All models MU-2B/-10/-15/-20/-25/-26: S/Nos. 005 through 347 (except S/Nos. 313,321).
- All models MU-2B-30/-35/-36: S/Nos. 501 through 696 (Except S/Nos. 652,661).
- All models MU-2B-25/-26/-26A/-40: S/Nos. 313SA/ 321SA, 348SA through 449SA.
- All models MU-2B-35/-36A/-60: S/Nos. 652SA, 661SA, 697SA through 1530 SA.
- Document: 1. Mitsubishi SB No. 176 Revision E, or
2. Mitsubishi Aircraft International SB No. SBO 31/27-005.
- Note: JCAB AD No. TCD-1001B-2-84 also refers.*
- Compliance: Unless already accomplished, as detailed in the requirement document.
- Background: This Directive has been amended to include revised requirement document references.