

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/MU-2/27.

---

### Mitsubishi MU-2 Series Aeroplanes

**AD/MU-2/27**

**Engine Control System  
Cable Pulleys - Replacement**

**7/2009**

Requirement: CANCELLED.

This AD is cancelled on 2 July 2009.

Background: This AD, issued in 1983, required replacement of the engine control system cable pulleys in accordance with Mitsubishi SB No. 035/27-006 because a batch of pulleys manufactured in 1975 were found to be cracked. The AD compliance was within 100 hours time in service after 30 November 1983. As all aircraft would have replaced these pulleys by now, the AD is no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

18 May 2009