

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/51

Autopilot Engage Switch Guard

3/92

Applicability: All Models MU-2 fitted with Bendix M4C or M4D autopilots.

Requirement: Action in accordance with MHI MU-2 Service Bulletin 076/22-008.

Note: JCAB TCD-3464-91 also refers.

Compliance: Within 100 hours time in service after 6 March 1992.

Background: To preclude the unintentional engagement of the autopilot.