
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-23/41.

Piper PA-23 (Apache and Aztec) Series Aeroplanes

AD/PA-23/41

Auxiliary Front Spar - Inspection

2/2009

Requirement: CANCELLED.

This AD is cancelled on 12 February 2009.

Background: This unique Australian AD specified a once-only inspection for cracking of the web of the auxiliary front spar (P/No. 16010) within 50 hours time in service after January 1971. This AD was not based on a Piper service document or USA AD. The AD is no longer required.



David Punshon
Delegate of the Civil Aviation Safety Authority

11 December 2008