
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-23/62.

Piper PA-23 (Apache and Aztec) Series Aeroplanes

AD/PA-23/62 Engine Lower Air Scoops and Fairings - Fluid 2/2009 Drainage Provision

Requirement: CANCELLED.

This AD is cancelled on 12 February 2009.

Background: This unique Australian AD specified installation of drainage holes in the engine lower air scoops and fairings in aircraft equipped with Airesearch turbochargers. Compliance was required in accordance with Piper SL No. 705 within 100 hours time in service after July 1974. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

22 December 2008