

Piper PA-23 (Apache and Aztec) Series Aeroplanes

---

**AD/PA-23/79                      Stabilator Assembly Lower Surface - Inspection                      10/79**

- Applicability:                      All model PA-23-250 (six place) with S/Nos. 27-7654001 to 27-7954044, fitted with stabilator S/Nos. referenced in Piper SB No. 606.
- Document:                              Piper SB No. 606.
- Compliance:                        Within 100 hours time in service after 31 October 1979 and there- after at intervals not exceeding 100 hours time in service until stabilator assembly is replaced or modified in accordance with SB No. 606.
- Background:                        The manufacturer has determined that the affected stabilator assemblies may not have proper bonding between the ribs and skins.