
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-25/31.


Piper PA-25 (Pawnee) Series Aeroplanes

AD/PA-25/31 Rapid Throttle Movement - Warning Placard 12/2008

Requirement: CANCELLED.

This AD is cancelled on 20 November 2008.

Background: This AD specified installation of a placard in accordance with Piper SL No. 644 which was raised to comply with USA AD 72-24-02. The placard was to advise that the throttle must not be opened rapidly. Compliance was required within 10 hours time in service after November 1972. The AD is no longer required.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

9 October 2008