
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-28/30.

Piper PA-28 Series Aeroplanes

AD/PA-28/30

Engine Mount Tubes - Inspection

7/2008

Requirement: CANCELLED.

This AD is cancelled on 3 July 2008.

Background: This Directive, issued in 1971, specified Piper SL No. 568 which called for periodic inspection for cracking of engine mount tubes until the engine mount was modified or replaced. As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

7 May 2008