
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-28/55.

Piper PA-28 Series Aeroplanes

AD/PA-28/55

Fuel Valve - Replacement

7/2008

Requirement: CANCELLED.

This AD is cancelled on 3 July 2008.

Background: This Directive specified Piper SB No. 444 which called for once-only replacement of a fuel valve. This Directive was not based on a US Directive. Compliance was required within 100 hours after March 1975 so the Directive is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

22 May 2008