

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-28/69.

---

### Piper PA-28 Series Aeroplanes

**AD/PA-28/69                      Engine Cowling - Drain Hole Provision                      7/2008**

Requirement:    CANCELLED.

This AD is cancelled on 3 July 2008.

Background:    This Directive specified Piper SB No. 580 which called for once-only modification to make a drain hole in the engine cowling. This Directive was not based on a US Directive. Compliance was required within 100 hours after February 1978 so the Directive is no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

22 May 2008