

Piper PA-28 Series Aeroplanes

AD/PA-28/83

**Battery Protection and Rear
Seat Installation - Inspection**

1/82

- Applicability: All models PA-28-151 & PA-28-161 with S/Nos. referenced in Piper SB No. 631B or with S/Nos. referenced in subsequent issues or revisions of that SB.
- Document: Piper SB No. 631B. (FAA AD 81-23-05 Refers).
- Compliance: 1. Part I: Before further flight after 25 November 1981, unless already accomplished.
2. Part II: Within 50 hours time in service after 25 November 1981, unless already accomplished.
- Background: The manufacturer has received reports of the seat base springs chafing the battery box cover and the springs subsequently contacting the battery terminals.