
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-32/36.

Piper PA-32 (Cherokee Six) Series Aeroplanes

AD/PA-32/36


Fuel Valve - Replacement

10/2008

Requirement: CANCELLED.

This AD is cancelled on 25 September 2008.

Background: This unique Australian AD specified replacement of the fuel valve in accordance with Piper SB No. 444. Compliance was required within 100 hours time in service after March 1975. The AD is no longer required.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

15 August 2008