
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-32/53.

Piper PA-32 (Cherokee Six) Series Aeroplanes

AD/PA-32/53


**Engine Control Rod End
Bearings - Inspection and Replacement**

10/2008

Requirement: CANCELLED.

This AD is cancelled on 25 September 2008.

Background: This AD specified inspection and replacement of engine control-rod end bearings. The inspection was not based on a Piper service document. USA AD 77-23-03 specified the same inspection. This AD and 77-23-03 required compliance within 25 hours time in service after November 1977 so the AD is no longer required.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

15 August 2008