
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/8.

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/8 **Wing Walk - Inspection and Modification** **11/2008**

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This unique Australian AD specified modification of the wing walk in accordance with Piper SL No. LDB-20. Compliance was required within 25 hours time in service after December 1972. The AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

9 September 2008